


AUDI A1 SPORTBACK: 1PUC191

Vinnnumber:	WAUZZZ8X5HB025413	Versionname:	1.6 TDI 85kW
First Registrationdate:	20/09/2016	Fiscalpower:	
Expertise Mileage:	92267	Power Kw:	85
Bodytype:	Hatchback	Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3730
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	
Steering wheel multifunction	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/88 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	211,80
-------------------	---------------


Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------


No pictures to display

Tailgate, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Bumper R, Dent(s), LI - Repair and paint (complete)	211,80
---	---------------





Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	