



AUDI A3: 1HUU486

Vinnnumber:	WAUZZZ8VXFA061549	Versionname:	A3 SB Ultra Attraction 110PK
First Registrationdate:	8/10/2014	Fiscalpower:	
Expertise Mileage:	53578	Power Kw:	81
Bodytype:		Body color	Red
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3522
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 2,5 mm	Fr.R.	Michelin: 2,5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm


Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1295,41
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Rear spoiler, Scratch(es), LI - Repair and paint (complete)	115,56
---	---------------



Alloy rim R L, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Sill outer R, Scratch(es), LI - Repair and paint (complete)	310,50



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Bumper grille, Broken, E - Replace	32,40
------------------------------------	-------



Front bumper, Bad repair, LI - Repair and paint (complete)	211,80
--	--------



Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------

