



ALFA ROMEO Giulietta: 1EHG243				
Vinnnumber:	ZAR94000007193674	Versionname:	GIULIETTA BER	
First Registrationdate:	3/12/2012	Fiscalpower:	Distinct.Start&Stop 105PK	
Expertise Mileage:	78375	Power Kw:	77	
Bodytype:	Hatchback	Body color	Dark Brown	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	3502	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Options				
Radio CD		Central consol F		
Windows electric F		Luggage cover		
Windows electric R		Front parking sensors		
Cruise Control		Rear parking sensors		
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Assistance equipment				
Spare wheel	Yes			
Total cost ex VAT		639,50		
Door R R, Dent(s), Acceptable		0,00		
No pictures to display				
Bonnet, Dent(s) and scratch(es), Acceptable		0,00		
No pictures to display				
Alloy rim F L, Scratch(es), Acceptable		0,00		
No pictures to display				
Roof, Dent(s), LI - Repair and paint (complete)		481,50		
No pictures to display				
Tailgate, Scratch(es), Acceptable		0,00		
No pictures to display				
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00		



Door R L, Dent(s), PDR - Knock out without painting	63,00
---	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display