



AUDI A3: 1DE0940

Vinnnumber:	WAUZZZ8P7CA148046	Versionname:	A3 S8 TDie
First Registrationdate:	24/04/2012	Attract.Start/Stop DPF	105PK
Expertise Mileage:	84009	Fiscalpower:	
Bodytype:	Break	Power Kw:	77
Gearbox:	MAN 5 VIT	Body color	Dark Grey
Transmission:		Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Battery functioning	Yes	Oil level	OK
Number of doors	5	Parking lot	2505
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT 1351,91

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Backrest cover R L, Unclasp(ed), N - Mount/Dismount	24,00
---	-------



Luggage space cover, Incomplete, Repair/replace (lump sum)	10,00
--	-------



Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Backrest cover R R, Unclasp(ed), N - Mount/Dismount	24,00
---	-------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------





Bumper R, Scratch(es), LI - Repair and paint (complete)

0,00



Windscreen, Scratch(es), E - Replace

0,00

