



BMW 3 BERLINE: 1LTX125

Vinnnumber:	WBA3D91010KL54275	Versionname:	2.0 316D (85KW) BERLINE
First Registrationdate:	3/12/2015	Fiscalpower:	
Expertise Mileage:	167107	Power Kw:	85
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2409
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


225/50/17/94 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Runflat	Yes
---------	-----

Total cost ex VAT	1554,68
Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80

Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete) 115,56



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete) 115,56



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68

