



|                                                         |                           |                       |                |
|---------------------------------------------------------|---------------------------|-----------------------|----------------|
| AUDI A6: 1HLF942                                        |                           |                       |                |
| Vinnnumber:                                             | WAUZZZ4G1EN188673         | Versionname:          | A6 AVANT 163PK |
| First Registrationdate:                                 | 19/08/2014                | Fiscalpower:          |                |
| Expertise Mileage:                                      | 132811                    | Power Kw:             | 120            |
| Bodytype:                                               | Break                     | Body color            | Anthracite     |
| Gearbox:                                                | MAN 6 VIT                 | Paint type            | Metalic        |
| Transmission:                                           | Front                     | Rims summer           | Aluminium      |
| Fueltype:                                               | Diesel                    | Oil level             | OK             |
| Battery functioning                                     | Yes                       | Parking lot           | 3528           |
| Number of doors                                         | 5                         |                       |                |
| Number of seats                                         | 5                         |                       |                |
| Number head rests                                       | 5                         |                       |                |
| Rims summer                                             | Aluminium                 |                       |                |
| Category                                                | Passenger Car             |                       |                |
| Oil level                                               | OK                        |                       |                |
| Registration Certificate Car (BE)                       | Yes                       |                       |                |
| Options                                                 |                           |                       |                |
| Radio CD                                                |                           | Central consol F      |                |
| Windows electric F                                      |                           | Luggage cover         |                |
| Windows electric R                                      |                           | Front parking sensors |                |
| Cruise Control                                          |                           | Rear parking sensors  |                |
| Steering wheel multifunctional                          |                           |                       |                |
| Seats F heated                                          |                           |                       |                |
| Radio multimedia                                        |                           |                       |                |
| Type of headlighting                                    | Headlighting Xenon        |                       |                |
| Type of GPS                                             | GPS big screen color      |                       |                |
| Type of Lining                                          | Lining leather            |                       |                |
| Type of climate control                                 | Autom climate control     |                       |                |
| Limited Technical Inspection                            |                           |                       |                |
| Airco functioning                                       | OK                        | Battery functioning   | Yes            |
| Tires wear profile                                      | OK                        | Power steering        | Yes            |
| Idle position                                           | OK                        | Sound engine          | OK             |
| Engine startingtime                                     | OK                        | Clutch test           | OK             |
| Exhaust gass                                            | OK                        | Wiper fluid level     | OK             |
| Handbrake                                               | OK                        | Transmission          | OK             |
|                                                         |                           | Lighting              | OK             |
|                                                         |                           | Wiperblades           | OK             |
| Degree of wear                                          |                           |                       |                |
| Summer tyres:                                           | 225/60/16/98 W LightMetal |                       |                |
|                                                         | Fr.L.                     | Michelin: 3 mm        | Fr.R.          |
|                                                         | Re.L.                     | Michelin: 5 mm        | Re.R.          |
|                                                         |                           | Michelin: 3 mm        | Michelin: 5 mm |
| Assistance equipment                                    |                           |                       |                |
| Repair kit                                              | Yes                       | Compressor            | Yes            |
| Total cost ex VAT                                       |                           |                       | 1741,82        |
| Door R R, Scratch(es), LI - Repair and paint (complete) |                           |                       | 382,02         |
|                                                         |                           |                       |                |
|                                                         |                           |                       |                |
| Roof, Scratch(es), LI - Repair and paint (complete)     |                           |                       | 577,80         |



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84



Bumper R, Chemical polution, LI - Repair and paint (complete) 254,16



Bonnet, Dent(s), PDR - Knock out without painting 63,00

