



RENAULT Megane: 1GDM417			
Vinnnumber:	VF1KZ140650212851	Versionname:	MEGANE GT Energy TomTom Ed.110PK
First Registrationdate:	8/01/2014	Fiscalpower:	
Expertise Mileage:	156354	Power Kw:	81
Bodytype:	Break	Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2324
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/55/16/91 H Steel			
	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1066,28
Bumper R, Dent(s), Smart repair			110,64



Bumper corner R L, Scratch(es), It - Spot repair	115,56
--	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Maintenance book, Missing, E - Replace	0,00
--	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wheel cover F R, Missing, E - Replace	30,00
---------------------------------------	-------




Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Bumper corner R R, Bad repair, Acceptable	0,00
---	------



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------

