



SEAT Alhambra: 1HFL602				
Vinnnumber:	VSSZZZ7NZEVS13880	Versionname:	ALHAMBRA	
First Registrationdate:	8/07/2014	Ecom.Reference DPF	136PK	
Expertise Mileage:	123295	Fiscalpower:		
Bodytype:	MPV	Power Kw:	100	
Gearbox:	MAN 6 VIT	Body color	Grey	
Transmission:		Paint type	Metalic	
Fueltype:	Diesel	Rims summer	Steel	
Battery functioning	Yes	Oil level	OK	
Number of doors	5	Parking lot	2821	
Number of seats	7			
Number head rests	7			
Rims summer	Steel			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
Windows electric F		Luggage cover		
Windows electric R		Front parking sensors		
Cruise Control		Rear parking sensors		
Steering wheel multifunctional		Type of Tow bar	No Tow bar	
Seats F heated				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	205/60/16/96 H Steel			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm
Assistance equipment				
Total cost ex VAT		115,56		
Roof, Chemical polution, 67 - Polish		0,00		
No pictures to display				
Door R L, Scratch(es), Acceptable		0,00		
No pictures to display				
Bumper R, Scratch(es), Acceptable		0,00		
No pictures to display				
Wheel cover F R, Scratch(es), Acceptable		0,00		
No pictures to display				
Wheel cover R L, Scratch(es), Acceptable		0,00		
No pictures to display				
Rocker panel inner F R, Dent(s), LI - Repair and paint (complete)		115,56		



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof pillar R, Dent(s), Acceptable	0,00
------------------------------------	------

No pictures to display

Foglight L, Broken, E - Replace	0,00
---------------------------------	------



Wing R R, Scratch(es), LI - Repair and paint (complete)	0,00
---	------



Door R R, Scratch(es), LI - Repair and paint (complete)	0,00
---	------

