



Renault MEGANE: 1HN148			
Vinnnumber:	VF1KZ140651433711	Versionname:	
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	182806	Power Kw:	81
Bodytype:	Break	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2309
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/55/16/91 H Steel			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment	
Spare wheel	Yes
Jack	Yes
Total cost ex VAT	907,60
Ignition key, Missing, E - Replace	150,00
No pictures to display	
Wing R R, Repaired, Acceptable	0,00
No pictures to display	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80





Wheel cover R R, Broken, E - Replace	30,00
--------------------------------------	-------



Luggage space cover, Missing, E - Replace	240,00
---	--------



Protection plate M, Strained , E - Replace	64,00
--	-------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

