


SKODA Superb: 1GMQ960

Vinnnumber:	TMBAJ73T2E9034525	Versionname:	SUPERB BER GreenLine Elegance 105PK
First Registrationdate:	12/03/2014	Fiscalpower:	
Expertise Mileage:	74316	Power Kw:	77
Bodytype:		Body color	Burgundy
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1127
Maintenance	BINNEN 28800 KM		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 2341,38

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 441,84





Rearlight R , Broken, E - Replace

132,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Scratch(es), Acceptable

0,00



Bumper F, Hole, Le - Replace and paint

862,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Door F R, Scratch(es), Acceptable

0,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00



Interior, Dirty, Chemical cleaning 152,58



Alloy rim R L, Scratch(es), Acceptable 0,00



Ignition key, Missing, E - Replace 150,00

No pictures to display

Door F R, Dent(s), PDR - Knock out without painting 63,00



Moulding windscreen R, Scratch(es), Acceptable 0,00



Bonnet, Stone chip(s), Acceptable 0,00

