



RENAULT Scenic: 1FCN183				
Vinnumber:	VF1JZ14K648918141	Versionname:	SCENIC Business 110PK	
First Registrationdate:	24/05/2013	Fiscalpower:		
Expertise Mileage:	103429	Power Kw:	81	
Bodytype:		Body color	Red	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Steel	
Fueltype:	Diesel	Oil level	OK	
Maintenance	NOT OK	Parking lot	3106	
Battery functioning	Yes			
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Steel			
Category	Passenger Car			
Oil level	OK			
Options				
Radio CD		Central consol F		
GPS storage	SD	Luggage cover		
GPS storage		Rear parking sensors		
Windows electric F				
Windows electric R				
Cruise Control				
Steering wheel multifunctional				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	205/60/16/92 H Steel			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm
Assistance equipment				
Spare wheel	Yes	Jack	Yes	
Total cost ex VAT			1292,49	
Door frame F R, Scratch(es), It - Spot repair			115,56	
				
Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)			342,35	



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------



Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R R, Dent(s), PDR - Knock out without painting	63,00
---	-------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display