



AUDI A6: 1HLE913			
Vinnnumber:	WAUZZZ4G4EN163816	Versionname:	A6 AVANT 136PK
First Registrationdate:	19/08/2014	Fiscalpower:	
Expertise Mileage:	168920	Power Kw:	100
Bodytype:	Break	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4511
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	225/60/16/102 W LightMetal			
	Fr.L.	Kleber: 7 mm	Fr.R.	Kleber: 7 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1223,56
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			95,00



Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	

Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Dent(s), Acceptable	0,00
No pictures to display	
Door frame R R, Scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Stone chip(s), Acceptable	0,00
No pictures to display	
Bumper R, Dent(s), Le - Replace and paint	766,80



Alloy rim F R, Scratch(es), Acceptable	0,00
No pictures to display	
Covering interior front pillar L, Burned, E - Replace	59,60



Wing F R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	302,16

