



BMW 3: 1FNJ376			
Vinnumber:	WBA3K11010F826734	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	28/08/2013	Fiscalpower:	
Expertise Mileage:	115106	Power Kw:	100
Bodytype:	Break	Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1123
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunction			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	225/50/17/94 W LightMetal			
	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment	
Total cost ex VAT	608,43
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), LI - Repair and paint (complete)	318,35



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------

