



|                         |                   |              |                       |
|-------------------------|-------------------|--------------|-----------------------|
| BMW X3: JD6717          |                   |              |                       |
| Vinnnumber:             | WBAWY510200E25878 | Versionname: | 3.0 XDRIVE30D (190KW) |
| First Registrationdate: | 1/01/2020         | Fiscalpower: | AUTO 4WD              |
| Expertise Mileage:      | 75096             | Power Kw:    | 190                   |
| Bodytype:               | SUV               | Body color   | Black                 |
| Gearbox:                | Automatic         | Paint type   | Metalic               |
| Transmission:           |                   | Rims summer  | Aluminium             |
| Fueltype:               | Diesel            | Oil level    | OK                    |
| Battery functioning     | Yes               | Parking lot  | 2602                  |
| Number of doors         | 5                 |              |                       |
| Number of seats         | 5                 |              |                       |
| Number head rests       | 5                 |              |                       |
| Rims summer             | Aluminium         |              |                       |
| Category                | Passenger Car     |              |                       |
| Oil level               | OK                |              |                       |

|                              |                       |                       |            |
|------------------------------|-----------------------|-----------------------|------------|
| Options                      |                       |                       |            |
| Radio CD                     |                       | Seats electric F L    |            |
| Windows electric F           |                       | Seats electric F R    |            |
| Windows electric R           |                       | Central consol F      |            |
| Cruise Control               |                       | Luggage cover         |            |
| Steering wheel multifunction |                       | Front parking sensors |            |
| Seats F heated               |                       | Rear parking sensors  |            |
| Radio multimedia             |                       | Type of Tow bar       | No Tow bar |
| Type of headlighting         | Headlighting Xenon    |                       |            |
| Type of GPS                  | GPS big screen color  |                       |            |
| Type of Lining               | Lining leather        |                       |            |
| Type of climate control      | Autom climate control |                       |            |

|                              |    |                     |     |
|------------------------------|----|---------------------|-----|
| Limited Technical Inspection |    |                     |     |
| Airco functioning            | OK | Battery functioning | Yes |
| Tires wear profile           | OK | Power steering      | Yes |
| Idle position                | OK | Sound engine        | OK  |
| Engine startingtime          | OK | Clutch test         | OK  |
| Exhaust gass                 | OK | Wiper fluid level   | OK  |
| Handbrake                    | OK | Transmission        | OK  |
|                              |    | Lighting            | OK  |
|                              |    | Wiperblades         | OK  |

|                |                           |                |                |
|----------------|---------------------------|----------------|----------------|
| Degree of wear |                           |                |                |
| Summer tyres:  | 225/60/17/99 Y LightMetal |                |                |
|                | Fr.L.                     | Michelin: 6 mm | Fr.R.          |
|                |                           |                | Michelin: 6 mm |
|                | Re.L.                     | Pirelli: 5 mm  | Re.R.          |
|                |                           |                | Pirelli: 5 mm  |

|                                            |     |            |      |
|--------------------------------------------|-----|------------|------|
| Assistance equipment                       |     |            |      |
| Repair kit                                 | Yes | Compressor | Yes  |
| Total cost ex VAT                          |     |            | 0,00 |
| Bumper corner R L, Scratch(es), Acceptable |     |            | 0,00 |
| No pictures to display                     |     |            |      |
| Door R L, Scratch(es), Acceptable          |     |            | 0,00 |
| No pictures to display                     |     |            |      |
| Alloy rim F R, Scratch(es), Acceptable     |     |            | 0,00 |
| No pictures to display                     |     |            |      |