



FORD Galaxy: 1FJV810				
Vinnnumber:	WF0MXXGBWMDA52320	Versionname:	GALAXY Econetic Trend	
First Registrationdate:	19/07/2013	Fiscalpower:	St&St DPF 115PK	
Expertise Mileage:	45911	Power Kw:	85	
Bodytype:		Body color	Grey	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Maintenance	GEEN MELDING	Parking lot	2720	
Maintenance	OK			
Battery functioning	Yes			
Number of doors	5			
Number of seats	7			
Number head rests	7			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Options				
Radio CD		Central consol F		
GPS storage	HD	Luggage cover		
GPS storage		Front parking sensors		
Windows electric F		Rear parking sensors		
Windows electric R		Type of Tow bar	No Tow bar	
Cruise Control				
Steering wheel multifunctional				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
	215/60/16/99 H LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT				1422,41
Door F R, Dent(s), PDR - Knock out without painting				159,00
				
				
Door trim F R, Crack, E - Replace				132,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

369,84



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Mirror side blinker R, Scratch(es), E - Replace

31,20



Wing R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

336,21



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Protection plate M, Hole, E - Replace

45,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Bumper corner R L, Scratch(es), Acceptable

0,00

No pictures to display