



RENAULT Clio: 1HRT434			
Vinnnumber:	VF15RJLOH51431665	Versionname:	CLIO IV BER e-Business St&St 90PK
First Registrationdate:	16/09/2014	Fiscalpower:	
Expertise Mileage:	72968	Power Kw:	66
Bodytype:	Hatchback	Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3732
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Windows electric F		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	185/65/15/88 T Steel			
	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1122,08
Wheel cover R R, Scratch(es), Acceptable			0,00
No pictures to display			
Roof, Dent(s), LI - Repair and paint (complete)			385,20





Bonnet, Chemical pollution, LI - Repair and paint (complete) 232,06



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 176,14



Luggage space cover, Dirty, Cleaning 50,00



Wheel cover F R, Scratch(es), E - Replace 24,00



Bumper F, Deformed / Strained, Le - Replace and paint 0,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display