



VOLKSWAGEN Golf: 1HLK876			
Vinnnumber:	WVWZZZAUZFP006408	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	20/08/2014	Fiscalpower:	
Expertise Mileage:	88462	Power Kw:	77
Bodytype:	Hatchback	Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4306
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
	195/65/15/91 H LightMetal		
Summer tyres:	Fr.L.	Continental: 3,5 mm	Fr.R.
	Re.L.	Continental: 5 mm	Re.R.

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			138,00
Outer door handle F R, Scratch(es), Acceptable			0,00
No pictures to display			
Seat cover R, Stain, Cleaning			25,00



Wing R L, Dent(s), Acceptable			0,00
No pictures to display			
Bumper corner R L, Scratch(es), Acceptable			0,00
No pictures to display			

Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	
Boot cover, Broken, E - Replace	50,00
	
Door R R, Dent(s), PDR - Knock out without painting	63,00
	