




MINI 5D: 1NAH146			
Vinnumber:	WMWXT310702B47328	Versionname:	1.5 COOPER D
First Registrationdate:	4/01/2016	Fiscalpower:	
Expertise Mileage:	84808	Power Kw:	85
Bodytype:		Body color	Light Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2716
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunction			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	175/65/15/84 H LightMetal		
	Fr.L.	Michelin: 5 mm	Fr.R.
			Michelin: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.
			Michelin: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			424,80
Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)			0,00



Bonnet, Dent(s), PDR - Knock out without painting	63,00
---	-------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Bumper R, Deformed / Strained, LI - Repair and paint (complete)	211,80
---	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper F R, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------

