



MINI 5D: 1NAH152			
Vinnumber:	WMWXT310802B47323	Versionname:	1.5 COOPER D
First Registrationdate:	4/01/2016	Fiscalpower:	
Expertise Mileage:	121071	Power Kw:	85
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2111
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunction			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	175/65/15/84 H LightMetal			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1002,63
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)			211,80




Door F L, Dent(s), Acceptable	0,00
No pictures to display	
Ignition key Missing, F - Replace	150,00

Ignition key, missing, E - Replace	100,00
No pictures to display	
Alloy rim F R, Scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Dent(s), LI - Repair and paint (complete)	290,08



Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Door F R, Dent(s), LI - Repair and paint (complete)	318,35



Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper grille, Broken, E - Replace	32,40

