


LEXUS RX: 1PPS212

Vinnnumber:	JTJBGMC302011236	Versionname:	3.5 450H 4WD EXECUTIVE LINE AUTO
First Registrationdate:	24/08/2016	Fiscalpower:	
Expertise Mileage:	37123	Power Kw:	193
Bodytype:		Body color	Blue
Gearbox:	Automatic	Paint type	Metallic
Transmission:	4 Wheel	Rims summer	Aluminium
Fueltype:	Hybrid Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	2601
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats R heated	
GPS storage		Seats electric F L	
GPS storage	HD	Seats electric F R	
Windows electric F		Seats F L ventilated	
Windows electric R		Seats F R ventilated	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	Tow bar fixed
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/55/20/102 V LightMetal			
Summer tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT	713,96
Alloy rim F L polished, Scratch(es), Acceptable	0,00
No pictures to display	
Rocker panel inner R L, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16



Wing moulding F R, Scratch(es), Smart repair	110,64
--	--------



Alloy rim R L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Rocker panel inner R R, Dent(s), Acceptable	0,00
---	------

No pictures to display

Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------

