





MERCEDES A80 CDI: 1GCS537				
Vinnumber:	WDD1760001J223630		Versionname:	A 180 CDI BE 109PK Aut.
First Registrationdate:	2/01/2014		Fiscalpower:	
Expertise Mileage:	180253		Power Kw:	80
Bodytype:			Body color	Black
Gearbox:	Automatic		Paint type	Metalic
Transmission:	Front		Rims summer	Aluminium
Fueltype:	Diesel		Oil level	OK
Maintenance	BU IN 19100 KM		Parking lot	3431
Maintenance	OK			
Battery functioning	Yes			
Number of doors	5			
Number of seats	5			
Number head rests	1			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Sun Roof electric		
GPS storage		Central consol F		
GPS storage	HD	Luggage cover		
Windows electric F		Front parking sensors		
Windows electric R		Rear parking sensors		
Cruise Control		Type of Tow bar		Tow bar removable
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Xenon			
Type of GPS	GPS big screen color			
Type of Lining	Lining semi-leather			
Type of climate control	Autom climate control			
Head-up Display				
Level control				
Limited Technical Inspection				
Airco functioning	OK	Battery functioning		Yes
Tires wear profile	OK	Power steering		Yes
Idle position	OK	Sound engine		OK
Engine startingtime	OK	Clutch test		OK
Exhaust gass	OK	Wiper fluid level		OK
Handbrake	OK	Transmission		OK
		Lighting		OK
		Wiperblades		OK
Degree of wear				
Summer tyres:	225/45/17/91 W LightMetal			
	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 7 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Assistance equipment				
Repair kit	Yes	Compressor		Yes
Total cost ex VAT				836,88
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)				95,00
				
Bonnet, Stone chip(s), LI - Repair and paint (complete)				290,08



Seat cover F R, Stain, Cleaning	25,00
---------------------------------	-------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Tailgate, Scratch(es), 67 - Polish	0,00
------------------------------------	------



Boot carpet, Dirty, Cleaning	25,00
------------------------------	-------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Windscreen, Repaired, P - Check	0,00
---------------------------------	------

