



MINI 5D: 1NAH126				
Vinnnumber:	WMWXT310802B47340	Versionname:	1.5 COOPER D	
First Registrationdate:	4/01/2016	Fiscalpower:		
Expertise Mileage:	84187	Power Kw:	85	
Bodytype:		Body color	Blue	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:		Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	2116	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Windows electric F		Luggage cover		
Windows electric R		Rear parking sensors		
Cruise Control		Type of Tow bar	No Tow bar	
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Manual climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	NOT OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Winter tyres:	175/65/15/84 H LightMetal			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			1189,80	
Wing R R, Scratch(es), It - Spot repair			115,56	
				
Bumper F, Scratch(es), LI - Repair and paint (complete)			211,80	



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	290,08
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F L, Scratch(es), It - Spot repair	115,56
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display