



VOLKSWAGEN Golf: 1HPX060				
Vinnnumber:	WVWZZZAUZFP534512	Versionname:	GOLF VAR Highline 105PK	
First Registrationdate:	9/09/2014	Fiscalpower:		
Expertise Mileage:	129709	Power Kw:	77	
Bodytype:	Break	Body color	Grey	
Gearbox:	MAN 5 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Maintenance	NOT OK	Parking lot	3601	
Battery functioning	Yes			
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
GPS storage		Luggage cover		
GPS storage	SD	Front parking sensors		
Windows electric F		Rear parking sensors		
Windows electric R		Type of Tow bar	No Tow bar	
Cruise Control				
Steering wheel multifunctional				
Seats F heated				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining semi-leather			
Type of climate control	Autom climate control			
Adaptive cruise control				
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Assistance equipment				
Emergency spare wheel	Yes	Jack	Yes	
Total cost ex VAT			906,60	
Interior, Dirty, Cleaning			150,00	





Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bonnet, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Maintenance, Maintenance, Execute	0,00
-----------------------------------	------



Rearlight L, Crack, E - Replace	114,00
---------------------------------	--------



Trunk lid covering R, Scratch(es), E - Replace	124,00
--	--------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



