



VOLVO V40: 1FNT377			
Vinnnumber:	YV1MV8461E2095486	Versionname:	V40 D2 Base 115PK
First Registrationdate:	2/09/2013	Fiscalpower:	
Expertise Mileage:	109068	Power Kw:	84
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3324
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunction	
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining leather and alcantara
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/50/17/93 W LightMetal			
	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	619,50
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	334,50
---	--------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display