



BMW 5 TOURING: 1KXR883			
Vinnnumber:	WBA5L11090G322979	Versionname:	2.0 518D (100KW) TOURING
First Registrationdate:	27/07/2015	Fiscalpower:	
Expertise Mileage:	101736	Power Kw:	100
Bodytype:	Break	Body color	Dark Brown
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2619
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Sun Roof electric
Cruise Control	Central consol F
Steering wheel multifunctional	Luggage cover
Seats F heated	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	245/45/18/96 Y LightMetal			
	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment	
Total cost ex VAT	277,44
Alloy rim F R, Scratch(es), E - Replace	277,44



Bumper F, Stone chip(s), Acceptable	0,00
No pictures to display	

Alloy rim R R, Scratch(es), Acceptable	0,00
No pictures to display	
Sill outer L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	