



BMW 5: 1HEX426

Vinnnumber:	WBA5J310X0D073630	Versionname:	5 TOURING 520d 163PK
First Registrationdate:	3/07/2014	Fiscalpower:	
Expertise Mileage:	180990	Power Kw:	120
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4833
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats R heated	
GPS storage	HD	Seats electric F R	
GPS storage		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunction		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/96 Y LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		932,32
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper F, Scratch(es), LI - Repair and paint (complete)		254,16





Sill outer L, Scratch(es), LI - Repair and paint (complete)	372,60
---	--------



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim R R polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper corner R L, Scratch(es), It - Spot repair	115,56
--	--------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

