



BMW 3: 1GRT832			
Vinnnumber:	WBA3K11040F831796	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	10/04/2014	Fiscalpower:	
Expertise Mileage:	170023	Power Kw:	100
Bodytype:	Break	Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2122
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	225/50/17/94 W LightMetal		
	Fr.L.	Dunlop: 3 mm	Fr.R.
	Re.L.	Dunlop: 5 mm	Re.R.
		Dunlop: 3 mm	Dunlop: 5 mm

Assistance equipment	
Total cost ex VAT	211,80
Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80





Bonnet, Chemical polution, Acceptable	0,00
No pictures to display	
Rear window, Scratch(es), Acceptable	0,00
No pictures to display	
Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	