



BMW 3: 1HTE600			
Vinnnumber:	WBA3K11030F835712	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	26/09/2014	Fiscalpower:	
Expertise Mileage:	76286	Power Kw:	100
Bodytype:	Break	Body color	Grey
Gearbox:	MAN 6 VIT	Body color	.
Transmission:	Back	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Battery functioning	Yes	Oil level	OK
Number of doors	5	Parking lot	.
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Level control			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/60/16/92 W LightMetal			
	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	274,80
Door F R, Scratch(es), Acceptable	0,00



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Roof, Dent(s), PDR - Knock out without painting

63,00

