



|                                   |                   |              |                            |
|-----------------------------------|-------------------|--------------|----------------------------|
| BMW 3: 1HNA045                    |                   |              |                            |
| Vinnnumber:                       | WBA3K91000F912180 | Versionname: | 3 TOURING 316da 116PK Aut. |
| First Registrationdate:           | 25/08/2014        | Fiscalpower: |                            |
| Expertise Mileage:                | 96552             | Power Kw:    | 85                         |
| Bodytype:                         | Break             | Body color   | Dark Blue                  |
| Gearbox:                          | Automatic         | Paint type   | Metalic                    |
| Transmission:                     |                   | Rims summer  | Aluminium                  |
| Fueltype:                         | Diesel            | Oil level    | OK                         |
| Battery functioning               | Yes               | Parking lot  | 2632                       |
| Number of doors                   | 5                 |              |                            |
| Number of seats                   | 5                 |              |                            |
| Number head rests                 | 5                 |              |                            |
| Rims summer                       | Aluminium         |              |                            |
| Category                          | Passenger Car     |              |                            |
| Oil level                         | OK                |              |                            |
| Registration Certificate Car (BE) | Yes               |              |                            |

|                                |                       |                       |               |
|--------------------------------|-----------------------|-----------------------|---------------|
| Options                        |                       |                       |               |
| Radio CD                       |                       | Central consol F      |               |
| Windows electric F             |                       | Luggage cover         |               |
| Windows electric R             |                       | Front parking sensors |               |
| Cruise Control                 |                       | Rear parking sensors  |               |
| Steering wheel multifunctional |                       | Type of Tow bar       | Tow bar fixed |
| Radio multimedia               |                       |                       |               |
| Type of headlighting           | Headlighting Xenon    |                       |               |
| Type of GPS                    | GPS big screen color  |                       |               |
| Type of Lining                 | Lining semi-leather   |                       |               |
| Type of climate control        | Autom climate control |                       |               |

|                              |    |                     |     |
|------------------------------|----|---------------------|-----|
| Limited Technical Inspection |    |                     |     |
| Airco functioning            | OK | Battery functioning | Yes |
| Tires wear profile           | OK | Power steering      | Yes |
| Idle position                | OK | Sound engine        | OK  |
| Engine startingtime          | OK | Clutch test         | OK  |
| Exhaust gass                 | OK | Wiper fluid level   | OK  |
| Handbrake                    | OK | Transmission        | OK  |
|                              |    | Lighting            | OK  |
|                              |    | Wiperblades         | OK  |

|                |                           |                   |       |                   |
|----------------|---------------------------|-------------------|-------|-------------------|
| Degree of wear |                           |                   |       |                   |
| Summer tyres:  | 225/50/17/94 W LightMetal |                   |       |                   |
|                | Fr.L.                     | Bridgestone: 5 mm | Fr.R. | Bridgestone: 5 mm |
|                | Re.L.                     | Hankook: 4 mm     | Re.R. | Hankook: 4 mm     |

|                                                              |        |
|--------------------------------------------------------------|--------|
| Assistance equipment                                         |        |
| Total cost ex VAT                                            | 401,80 |
| Wing F R, Scratch(es), Acceptable                            | 0,00   |
| No pictures to display                                       |        |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00  |



|                                                              |       |
|--------------------------------------------------------------|-------|
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--------------------------------------------------------------|-------|



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

