


MERCEDES A: 1KXN176

Vinnnumber:	WDD1760121V083393	Versionname:	1.5 A 180 CDI
First Registrationdate:	24/07/2015	Fiscalpower:	
Expertise Mileage:	50189	Power Kw:	80
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4631
Maintenance	SERV A IN 189 DAGEN		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Type of Tow bar
Windows electric F	No Tow bar
Windows electric R	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/95 V Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	326,99
Wheel cover R R, Broken, E - Replace	30,00




Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Wheel cover F L, Scratch(es), E - Replace	30,00
---	-------



Rearview mirror housing R, Scratch(es), 67 - Polish	55,19
---	-------



Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Rear window, Not original part, Remove lettering	0,00
--	------

