



MINI : 1LRS656			
Vinnnumber:	WMWXT110402B80095	Versionname:	1.5 ONE D
First Registrationdate:	17/11/2015	Fiscalpower:	
Expertise Mileage:	72464	Power Kw:	70
Bodytype:	Hatchback	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1230
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	175/65/15/84 H LightMetal			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Hankook: 3 mm	Re.R.	Hankook: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1777,98
Tailgate, Bad repair, LI - Repair and paint (complete)			301,68



Roof, Scratch(es), LI - Repair and paint (complete)	481,50
---	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
	
Wheel arch cover F L, Scratch(es), E - Replace	75,00
	
Roof pillar L, Scratch(es), Acceptable	0,00
No pictures to display	
Maintenance book, Missing, E - Replace	0,00
	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Bonnet, Dent(s), Acceptable	0,00
No pictures to display	
Certificate Of Conformity, Missing, E - Replace	150,00
	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing trim R R, Scratch(es), E - Replace	84,00
	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), I - Repair	100,00
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Bumper F M, Dent(s), Acceptable	0,00
No pictures to display	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R L, Scratch(es), I - Repair	100,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing trim R R, Scratch(es), E - Replace 84,00

