



PEUGEOT 3008: 1FTE437

Vinnumber:	VF30U9HD8D5168209	Versionname:	3008 e-HDi Allure STT FAP BMP 115PK Aut.
First Registrationdate:	17/10/2013	Fiscalpower:	
Expertise Mileage:	104600	Power Kw:	84
Bodytype:		Body color	Brown
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4716
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Panoramic roof
GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Head-up Display		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/50/17/98 V LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	-----	------	-----

Total cost ex VAT	677,31
-------------------	--------

Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------


No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------





Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F L, Scratch(es), It - Spot repair	115,56
---	--------



Foglight L, Scratch(es), Forfeit	110,00
----------------------------------	--------



Bumper moulding F, Dent(s), E - Replace	38,40
---	-------

