



OPEL Zafira: 1HKA228

Vinnnumber:	WOLPE9E39E2103886	Versionname:	ZAFIRA TOURER
First Registrationdate:	6/08/2014	Fiscalpower:	ecoFL.Cosmo S/S 136PK
Expertise Mileage:	155423	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1310
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 H LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1792,05
Bumper R, Scratch(es), LI - Repair and paint (complete)			235,80



Floor covering F L, Hole, E - Replace

252,00

 		Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	358,50
 		Bonnet, Dent(s), PDR - Paintless dent repair	142,20
 		Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
 		Door F L, Scratch(es), Acceptable	0,00
No pictures to display		Door R L, Scratch(es), Acceptable	0,00
No pictures to display		Seat cover F L, Damaged, Acceptable	0,00
 		Wing F R, Dent(s), Acceptable	0,00
No pictures to display		Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
 		Rearlight L, Crack, E - Replace	114,00
 		Roof, Dent(s), PDR - Paintless dent repair	63,00
 			