


BMW 3: 1HEX924

Vinnumber:	WBA3D110X0J627656	Versionname:	3 BER 318d 136PK
First Registrationdate:	3/07/2014	Fiscalpower:	
Expertise Mileage:	78124	Power Kw:	100
Bodytype:	Berline	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3627
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Front parking sensors
GPS storage	HD Rear parking sensors
Windows electric F	Type of Tow bar
Windows electric R	No Tow bar
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	205/60/16/92 H LightMetal			
	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			290,08
Door F L, Scratch(es), Acceptable			0,00
No pictures to display			
Wing R L, Scratch(es), Acceptable			0,00
No pictures to display			
Door R R, Scratch(es), Acceptable			0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair

0,00



Seat cover F L, Tear, Acceptable

0,00



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Scratch(es), Acceptable

0,00

No pictures to display