



VOLKSWAGEN Caddy: 1JVG540

Vinnumber:	WV2ZZZ2KZFX057865	Versionname:	D
First Registrationdate:	24/11/2014	Fiscalpower:	
Expertise Mileage:	171412	Power Kw:	75
Bodytype:		Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2326
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/94 V Steel			
	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 6 mm	Re.R.	Kleber: 6 mm

Assistance equipment

Total cost ex VAT	500,20
Sill outer R, Bad repair, P - Check	0,00



Bumper R, Scratch(es), E - Replace	415,20
------------------------------------	--------



Internal Boot Lining R, Scratch(es), E - Replace

0,00



Sliding door R, Bad repair, P - Check

0,00



Seat cover F L, Stain, Cleaning

25,00



Wing R R, Bad repair, P - Check

0,00




Internal Boot Lining L, Scratch(es), E - Replace

0,00



Bodywork, Damaged, Acceptable

0,00



Trunk lid covering R, Damaged, E - Replace

35,00



Seat cover F R, Stain, Cleaning

25,00

