



VOLKSWAGEN GOLF VII: CS0366

Vinnumber:	VWVZZZAUZGP032738	Versionname:	2.0 TDI 110KW HIGHLINE DSG
First Registrationdate:	1/01/2020	Fiscalpower:	
Expertise Mileage:	43616	Power Kw:	110
Bodytype:	Hatchback	Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3232
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Seats electric F L
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 W LightMetal			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			361,80
Ignition key, Missing, E - Replace			150,00
<i>No pictures to display</i>			
Tailgate, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R L polished, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F R polished, Scratch(es), Acceptable			0,00

Alloy rim R polished, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display