



VOLKSWAGEN SHARAN: EG2017

Vinnumber:	WVWZZZ7NZGV218909	Versionname:	2.0 CR TDI 135KW HIGHLINE BMT
First Registrationdate:	8/12/2015	Fiscalpower:	
Expertise Mileage:	124558	Power Kw:	135
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3606
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Sun Roof electric
GPS storage	Panoramic roof
GPS storage	SD Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather and alcantara
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	225/50/17/98 H LightMetal			
	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 8 mm	Re.R.	Continental: 8 mm

Assistance equipment

Total cost ex VAT	1134,27
Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing trim R R, Scratch(es), LI - Repair and paint (complete)	150,00




Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Interior, Dirty, Acceptable	0,00
-----------------------------	------

No pictures to display

Bumper F, Chemical polution, LI - Repair and paint (complete)	254,16
---	--------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09
---	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display