


VOLKSWAGEN Touran: 1HZR609

Vinnumber:	WVGZZZ1TZFW029988	Versionname:	TOURAN Highline BMT St/St 7pl.DSG 105PK
First Registrationdate:	7/11/2014	Fiscalpower:	
Expertise Mileage:	134819	Power Kw:	77
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2732
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Total cost ex VAT	721,44
Door panel R R, Scratch(es), Smart repair	110,64



Rearlight L, Broken, E - Replace

114,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Door panel F L, Stain, Acceptable

0,00



Rear window, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s), Acceptable

0,00

No pictures to display

Armrest R M, Stain, Acceptable

0,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Seat cover F L, Stain, Acceptable

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

