



VOLVO V40: 1GEV469

Vinnumber:	YV1MV8481E2129392	Versionname:	V40 D2 Base 115PK
First Registrationdate:	20/01/2014	Fiscalpower:	
Expertise Mileage:	68672	Power Kw:	84
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2824
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	No	Compressor	Yes
------------	-----------	------------	------------

Total cost ex VAT	2085,71
-------------------	----------------

Tyre repair kit, Missing, E - Replace	210,53
---------------------------------------	---------------



Seat cover F L, Hole, E - Replace	360,00
	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Mirror side blinker R, Broken, E - Replace	30,00
	
Interior, Dirty, Cleaning	100,00
	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Roof, Chemical polution, LI - Repair and paint (complete)	481,50
	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------

