



OPEL COMBO: 1KJK712

Vinnumber:	W0L6ZYC1AF9562846	Versionname:	1.3 CDTI 66KW 2.0T SWB
First Registrationdate:	12/05/2015	Fiscalpower:	
Expertise Mileage:	48049	Power Kw:	66
Bodytype:	Transporter	Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2733
Number of doors	5		
Number of seats	2		
Number head rests	2		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 T Steel			
Summer tyres:	Fr.L.	Goodyear: 3,5 mm	Fr.R.	Goodyear: 3,5 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			150,00
Bonnet, Scratch(es), Acceptable			0,00
No pictures to display			
Wing R R, Scratch(es), Acceptable			0,00
No pictures to display			
Wing R L, Scratch(es), Acceptable			0,00
No pictures to display			
GPS, Missing, E - Replace			150,00
No pictures to display			
Door R R, Dent(s) and scratch(es), Acceptable			0,00
No pictures to display			
Door F L, Scratch(es), Acceptable			0,00

No pictures to display