



VOLVO V40: 1HZV990				
Vinnumber:	YV1MV8461F2212309	Versionname:	V40 D2 Base 115PK	
First Registrationdate:	12/11/2014	Fiscalpower:		
Expertise Mileage:	138985	Power Kw:	84	
Bodytype:		Body color	Black	
Gearbox:	MAN 6 VIT	Paint type	Metallic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	1525	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
GPS storage	HD	Luggage cover		
GPS storage		Rear parking sensors		
Windows electric F				
Cruise Control				
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining semi-leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
	205/50/17/89 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			921,60	
Ignition key, Missing, E - Replace			150,00	



Door F L, Dent(s), PDR - Paintless dent repair 63,00



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Rear window, Scratch(es), E - Replace 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80





Door R R, Scratch(es), Acceptable

0,00

No pictures to display