


SKODA OCTAVIA COMBI: 1LRP346

Vinnumber:	TMBJG9NE2G0121809	Versionname:	1.6 CRTDI 81KW GREENTEC STYLE
First Registrationdate:	16/11/2015	Fiscalpower:	
Expertise Mileage:	140520	Power Kw:	81
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2229
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Seats electric F L
Windows electric R	Seats electric F R
Cruise Control	Sun Roof electric
Steering wheel multifunctional	Central consol F
Seats F heated	Luggage cover
Radio multimedia	Front parking sensors
Type of headlighting	Rear parking sensors
Type of GPS	Type of Tow bar
Type of Lining	No Tow bar
Type of climate control	
Headlighting Halogen	
GPS big screen color	
Lining semi-leather	
Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/17/91 H LightMetal				
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			531,35
Wing R R, Repaired, Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Dent(s), PDR - Paintless dent repair			63,00



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display