



SKODA Superb: 1FCX526

Vinnumber:	TMBAJ73T2D9052618	Versionname:	SUPERB BER GreenLine Ambition DPF 105PK
First Registrationdate:	28/05/2013	Fiscalpower:	
Expertise Mileage:	184585	Power Kw:	77
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2719
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	721,24
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Bonnet, Scratch(es), Acceptable	0,00
No pictures to display	
Tailgate, Scratch(es), LI - Repair and paint (complete)	362,02
	
Door F R, Dent(s), Acceptable	0,00
No pictures to display	
Roof pillar R, Scratch(es), LI - Repair and paint (complete)	264,22
	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	