


**VOLKSWAGEN Polo: 1HSC104**

|                                   |                          |              |                                  |
|-----------------------------------|--------------------------|--------------|----------------------------------|
| Vinnumber:                        | <b>WVWZZZ6RZFY132099</b> | Versionname: | <b>POLO Comfortline BMT 90PK</b> |
| First Registrationdate:           | <b>18/09/2014</b>        | Fiscalpower: |                                  |
| Expertise Mileage:                | <b>104261</b>            | Power Kw:    | <b>66</b>                        |
| Bodytype:                         |                          | Body color   | <b>Grey</b>                      |
| Gearbox:                          | <b>MAN 5 VIT</b>         | Paint type   | <b>Metalic</b>                   |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b>                 |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                        |
| Maintenance                       | <b>BINNEN 25100</b>      | Parking lot  | <b>3313</b>                      |
| Maintenance                       | <b>OK</b>                |              |                                  |
| Battery functioning               | <b>Yes</b>               |              |                                  |
| Number of doors                   | <b>5</b>                 |              |                                  |
| Number of seats                   | <b>5</b>                 |              |                                  |
| Number head rests                 | <b>5</b>                 |              |                                  |
| Rims summer                       | <b>Aluminium</b>         |              |                                  |
| Category                          | <b>Passenger Car</b>     |              |                                  |
| Oil level                         | <b>OK</b>                |              |                                  |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                  |

**Options**

|                                |                               |                       |                   |
|--------------------------------|-------------------------------|-----------------------|-------------------|
| Radio CD                       |                               | Central consol F      |                   |
| GPS storage                    | <b>SD</b>                     | Luggage cover         |                   |
| GPS storage                    |                               | Front parking sensors |                   |
| Windows electric F             |                               | Rear parking sensors  |                   |
| Windows electric R             |                               | Type of Tow bar       | <b>No Tow bar</b> |
| Cruise Control                 |                               |                       |                   |
| Steering wheel multifunctional |                               |                       |                   |
| Radio multimedia               |                               |                       |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>   |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>   |                       |                   |
| Type of Lining                 | <b>Lining fabrics</b>         |                       |                   |
| Type of climate control        | <b>Manual climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>185/60/15/88 H LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Goodyear: 4 mm</b> | Fr.R. | <b>Goodyear: 4 mm</b> |
|               | Re.L.                            | <b>Pirelli: 4 mm</b>  | Re.R. | <b>Pirelli: 4 mm</b>  |

**Assistance equipment**

|                                                |            |      |                |
|------------------------------------------------|------------|------|----------------|
| Spare wheel                                    | <b>Yes</b> | Jack | <b>Yes</b>     |
| Total cost ex VAT                              |            |      | <b>2326,94</b> |
| Door F R, Dent(s), PDR - Paintless dent repair |            |      | <b>63,00</b>   |



Interior, Dirty, Cleaning

25,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Door R R, Scratch(es), Acceptable

0,00



Roof, Dent(s), LI - Repair and paint (complete)

385,20



Door R L, Scratch(es), LI - Repair and paint (complete)

254,68



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

169,44



Wing R L, Dent(s), Acceptable

0,00



Bumper R, Dent(s), LI - Repair and paint (complete)

169,44



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s), LI - Repair and paint (complete)

232,06



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Scratch(es), Acceptable

0,00



Door F L, Rust, LI - Repair and paint (complete)

254,68



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Roof pillar R, Dent(s), PDR - Paintless dent repair

63,00



Tailgate, Dent(s), PDR - Paintless dent repair

63,00



Engine protective plate, Broken, E - Replace

98,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00

