



MERCEDES A180: 1FTG381

Vinnumber:	WDD1760121J194180	Versionname:	CDI BE 109PK
First Registrationdate:	17/10/2013	Fiscalpower:	
Expertise Mileage:	87281	Power Kw:	80
Bodytype:	Hatchback	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2306
Maintenance	A1 SERVICE OVER 318 DAGEN		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	1		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Manual climate control

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	225/45/17/91 H LightMetal			
	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			405,00
Seat cover F L, Stain, Cleaning			25,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Scratch(es), Acceptable

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), Acceptable

0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

