


AUDI A3: 1GIV548

Vinnumber:	WAUZZZ8V0EA137729	Versionname:	A3 SB Quattro Ambition S-tr.184PK Aut.
First Registrationdate:	19/02/2014	Fiscalpower:	
Expertise Mileage:	151142	Power Kw:	135
Bodytype:		Body color	Blue
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3410
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			2001,43
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

366,35



Door F R, Dent(s), PDR - Paintless dent repair

63,00



Floor covering R, Burned, Smart repair

64,32



Covering interior B pillar L, Burned, Smart repair

110,64




Mats, Burned, Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Ignition key, Missing, E - Replace

0,00



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

358,50



Floor covering F R, Burned, Smart repair

64,32



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

268,18



MOT Certificate, Incomplete, P - Check

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper corner R R, Scratch(es), Acceptable

0,00

No pictures to display

Ceiling, Dirty, Cleaning

50,00



Floor covering F L, Burned, Smart repair

64,32



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

