


FORD C-MAX: 1GPP430

Vinnumber:	WF0JXXWPBJEY52156	Versionname:	C-MAX Titanium St/St 115PK
First Registrationdate:	26/03/2014	Fiscalpower:	
Expertise Mileage:	112870	Power Kw:	85
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4204
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Fulda: 3 mm	Fr.R.	Fulda: 3 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			157,56
Tires, Not original part, Acceptable			0,00
<i>No pictures to display</i>			
Tailgate, Dent(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F R, Scratch(es), Acceptable			0,00

No pictures to display

Bumper spoiler F, Scratch(es), E - Replace	42,00
--	-------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door panel R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Glove compartment lid, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Ceiling, Stain, Acceptable	0,00
----------------------------	------

No pictures to display

Bumper F, Scratch(es), It - Spot repair	115,56
---	--------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rear bulkhead lining, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Handbrake cover, Worn, Acceptable	0,00
-----------------------------------	------

No pictures to display

Brand badge R, Worn, Acceptable	0,00
---------------------------------	------

No pictures to display

Door panel R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display