



BMW 5: 1HHC806

Vinnumber:	WBA5J11050D336143	Versionname:	5 TOURING 518d 136PK
First Registrationdate:	22/07/2014	Fiscalpower:	
Expertise Mileage:	182324	Power Kw:	100
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	2805
Maintenance	SERVICE -600KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Seats electric F L
GPS storage	Seats electric F R
GPS storage	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	-----	------------	-----

Total cost ex VAT	342,36
-------------------	--------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display	
------------------------	--

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display	
------------------------	--

Windscreen, Stone chip(s), Windscreen repair		88,20
  		
Seat cover F R, Worn, Acceptable		0,00
No pictures to display		
Maintenance, Maintenance, Execute		0,00
		
Wing R L, Dent(s), Acceptable		0,00
No pictures to display		
Door R R, Dent(s), Acceptable		0,00
No pictures to display		
Bumper F, Scratch(es), LI - Repair and paint (complete)		254,16
  		
		
Alloy rim F R, Scratch(es), Acceptable		0,00
No pictures to display		
Seat cover F L, Worn, Acceptable		0,00
No pictures to display		
Backrest cover F L, Worn, Acceptable		0,00
No pictures to display		
Armrest L, Worn, Acceptable		0,00
No pictures to display		