



**VOLKSWAGEN Passat: 1HJH431**

|                                   |                          |              |                                                 |
|-----------------------------------|--------------------------|--------------|-------------------------------------------------|
| Vinnumber:                        | <b>WVWZZZ3CZFE032671</b> | Versionname: | <b>PASSAT VAR Comfortline BMT DSG 105PK Aut</b> |
| First Registrationdate:           | <b>1/08/2014</b>         | Fiscalpower: |                                                 |
| Expertise Mileage:                | <b>184600</b>            | Power Kw:    | <b>77</b>                                       |
| Bodytype:                         |                          | Body color   | <b>Black</b>                                    |
| Gearbox:                          | <b>Automatic</b>         | Paint type   | <b>Metalic</b>                                  |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b>                                |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                                       |
| Maintenance                       | <b>3400</b>              | Parking lot  | <b>4714</b>                                     |
| Maintenance                       | <b>- 35 DAGEN</b>        |              |                                                 |
| Maintenance                       | <b>NOT OK</b>            |              |                                                 |
| Battery functioning               | <b>Yes</b>               |              |                                                 |
| Number of doors                   | <b>5</b>                 |              |                                                 |
| Number of seats                   | <b>5</b>                 |              |                                                 |
| Number head rests                 | <b>5</b>                 |              |                                                 |
| Rims summer                       | <b>Aluminium</b>         |              |                                                 |
| Category                          | <b>Passenger Car</b>     |              |                                                 |
| Oil level                         | <b>OK</b>                |              |                                                 |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                                 |

**Options**

|                                |                              |                       |                      |
|--------------------------------|------------------------------|-----------------------|----------------------|
| Radio CD                       |                              | Sun Roof electric     |                      |
| GPS storage                    |                              | Panoramic roof        |                      |
| GPS storage                    | <b>HD</b>                    | Central consol F      |                      |
| Windows electric F             |                              | Luggage cover         |                      |
| Windows electric R             |                              | Front parking sensors |                      |
| Cruise Control                 |                              | Rear parking sensors  |                      |
| Steering wheel multifunctional |                              | Type of Tow bar       | <b>Tow bar fixed</b> |
| Seats F heated                 |                              |                       |                      |
| Radio multimedia               |                              |                       |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                      |
| Type of Lining                 | <b>Lining leather</b>        |                       |                      |
| Type of climate control        | <b>Autom climate control</b> |                       |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                           |                |       |                |
|---------------|---------------------------|----------------|-------|----------------|
| Winter tyres: | 215/55/16/97 H LightMetal |                |       |                |
|               | Fr.L.                     | Semperit: 5 mm | Fr.R. | Semperit: 5 mm |
|               | Re.L.                     | Semperit: 6 mm | Re.R. | Semperit: 6 mm |

**Assistance equipment**

|                                                 |            |            |               |
|-------------------------------------------------|------------|------------|---------------|
| Repair kit                                      | <b>Yes</b> | Compressor | <b>Yes</b>    |
| Total cost ex VAT                               |            |            | <b>838,92</b> |
| Internal Boot Lining R, Scratch(es), Acceptable |            |            | <b>0,00</b>   |

No pictures to display

|                                             |        |
|---------------------------------------------|--------|
| Alloy rim R R, Scratch(es), Acceptable      | 0,00   |
| <i>No pictures to display</i>               |        |
| Door frame F L, Scratch(es), Acceptable     | 0,00   |
| <i>No pictures to display</i>               |        |
| Bonnet, Dent(s) and scratch(es), Acceptable | 0,00   |
| <i>No pictures to display</i>               |        |
| Wing F R, Scratch(es), It - Spot repair     | 115,56 |



|                                     |        |
|-------------------------------------|--------|
| Wing F L, Dent(s), It - Spot repair | 115,56 |
|-------------------------------------|--------|



|                                               |        |
|-----------------------------------------------|--------|
| Seat F L compl, Worn, Acceptable              | 0,00   |
| <i>No pictures to display</i>                 |        |
| Door F L, Dent(s) and scratch(es), Acceptable | 0,00   |
| <i>No pictures to display</i>                 |        |
| Tires, Not original part, Acceptable          | 0,00   |
| <i>No pictures to display</i>                 |        |
| Door F R, Dent(s) and scratch(es), Acceptable | 0,00   |
| <i>No pictures to display</i>                 |        |
| Headlight R, Scratch(es), E - Replace         | 396,00 |



|                                                         |        |
|---------------------------------------------------------|--------|
| Bumper R, Scratch(es), Acceptable                       | 0,00   |
| <i>No pictures to display</i>                           |        |
| Door R R, Scratch(es), Acceptable                       | 0,00   |
| <i>No pictures to display</i>                           |        |
| Bumper R, Repaired, Acceptable                          | 0,00   |
| <i>No pictures to display</i>                           |        |
| Door R L, Dent(s) and scratch(es), Acceptable           | 0,00   |
| <i>No pictures to display</i>                           |        |
| Trunk lid covering R, Scratch(es), Acceptable           | 0,00   |
| <i>No pictures to display</i>                           |        |
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 211,80 |





|                                   |      |
|-----------------------------------|------|
| Maintenance, Maintenance, Execute | 0,00 |
|-----------------------------------|------|



|                                                 |      |
|-------------------------------------------------|------|
| Internal Boot Lining L, Scratch(es), Acceptable | 0,00 |
|-------------------------------------------------|------|

No pictures to display

|                                                |      |
|------------------------------------------------|------|
| Outer door handle R R, Scratch(es), Acceptable | 0,00 |
|------------------------------------------------|------|

No pictures to display

|                                  |      |
|----------------------------------|------|
| Door panel F L, Worn, Acceptable | 0,00 |
|----------------------------------|------|

No pictures to display

|                                                         |      |
|---------------------------------------------------------|------|
| Electricity circuit, Not functioning (well), Acceptable | 0,00 |
|---------------------------------------------------------|------|

No pictures to display

|                                    |      |
|------------------------------------|------|
| Roof pillar R, Dent(s), Acceptable | 0,00 |
|------------------------------------|------|

No pictures to display

|                                               |      |
|-----------------------------------------------|------|
| Wing R R, Dent(s) and scratch(es), Acceptable | 0,00 |
|-----------------------------------------------|------|

No pictures to display