



|                                   |                   |              |            |
|-----------------------------------|-------------------|--------------|------------|
| AUDI A4: 1GRS291                  |                   |              |            |
| Vinnumber:                        | WAUZZZ8K2EA117651 | Versionname: | TDie 136PK |
| First Registrationdate:           | 10/04/2014        | Fiscalpower: |            |
| Expertise Mileage:                | 160900            | Power Kw:    | 100        |
| Bodytype:                         | Berline           | Body color   | Red        |
| Gearbox:                          | MAN 6 VIT         | Paint type   | Metallic   |
| Transmission:                     | Front             | Rims summer  | Aluminium  |
| Fueltype:                         | Diesel            | Oil level    | OK         |
| Maintenance                       | OK                | Parking lot  | 2112       |
| Maintenance                       | OVER 15900 KM     |              |            |
| Battery functioning               | Yes               |              |            |
| Number of doors                   | 4                 |              |            |
| Number of seats                   | 5                 |              |            |
| Number head rests                 | 5                 |              |            |
| Rims summer                       | Aluminium         |              |            |
| Category                          | Passenger Car     |              |            |
| Oil level                         | OK                |              |            |
| Registration Certificate Car (BE) | Yes               |              |            |

|                                |                       |                      |            |
|--------------------------------|-----------------------|----------------------|------------|
| Options                        |                       |                      |            |
| GPS storage                    | DVD                   | Central consol F     |            |
| GPS storage                    |                       | Luggage cover        |            |
| Windows electric F             |                       | Rear parking sensors |            |
| Windows electric R             |                       | Type of Tow bar      | No Tow bar |
| Cruise Control                 |                       |                      |            |
| Steering wheel multifunctional |                       |                      |            |
| Seats F heated                 |                       |                      |            |
| Radio multimedia               |                       |                      |            |
| Type of headlighting           | Headlighting Halogen  |                      |            |
| Type of GPS                    | GPS big screen color  |                      |            |
| Type of Lining                 | Lining fabrics        |                      |            |
| Type of climate control        | Autom climate control |                      |            |

|                              |    |                     |     |
|------------------------------|----|---------------------|-----|
| Limited Technical Inspection |    |                     |     |
| Airco functioning            | OK | Battery functioning | Yes |
| Tires wear profile           | OK | Power steering      | Yes |
| Idle position                | OK | Sound engine        | OK  |
| Engine startingtime          | OK | Clutch test         | OK  |
| Exhaust gass                 | OK | Wiper fluid level   | OK  |
| Handbrake                    | OK | Transmission        | OK  |
|                              |    | Lighting            | OK  |
|                              |    | Wiperblades         | OK  |

|                |                           |                  |       |                  |
|----------------|---------------------------|------------------|-------|------------------|
| Degree of wear |                           |                  |       |                  |
| Winter tyres:  | 205/60/16/96 H LightMetal |                  |       |                  |
|                | Fr.L.                     | Vredestein: 6 mm | Fr.R. | Vredestein: 6 mm |
|                | Re.L.                     | Goodyear: 6 mm   | Re.R. | Goodyear: 6 mm   |

|                                                        |     |            |        |
|--------------------------------------------------------|-----|------------|--------|
| Assistance equipment                                   |     |            |        |
| Repair kit                                             | Yes | Compressor | Yes    |
| Total cost ex VAT                                      |     |            | 318,35 |
| Door R L, Bad repair, LI - Repair and paint (complete) |     |            | 318,35 |



|                                        |      |
|----------------------------------------|------|
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
|----------------------------------------|------|



|                                           |      |
|-------------------------------------------|------|
| Engine, Not functioning (well), P - Check | 0,00 |
|-------------------------------------------|------|



|                               |      |
|-------------------------------|------|
| Wing F L, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|



|                                        |      |
|----------------------------------------|------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
|----------------------------------------|------|



|                                   |      |
|-----------------------------------|------|
| Wing R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

